



Greater Cambridge Partnership

CAMBOURNE TO CAMBRIDGE

Environmental Statement

Technical Report 7, Appendix TR7.3: Trial
Trenching Report






MEMO – C2C Scheme Trial Trenching Status


Figures 1-5 provide an indicative representation of the trial trenching along the C2C Scheme. The Trial Trenching campaign, although largely complete, is still underway, with the remaining trenches to be excavated once access has been obtained. Once all trenches have been excavated and assessed, Appendix TR7.3 will be updated with the final Trial Trenching Report.

FIGURE // Trench Status 1/5



The Site		Trench Status	
	Site Boundary		Excavated
	Services - Buffer		Unexcavated

0 0.1 0.2 km




PROJECT // 4513E - Cambourne to Cambridge Busway

DESCRIPTION // Trench status


Contains OS data © Crown Copyright 2023 Open Government Licence 3.0

WP 230621

FIGURE // Trench Status 2/5



- | The Site | | Trench Status | |
|--|-------------------|---|-------------|
|  | Site Boundary |  | Excavated |
|  | Services - Buffer |  | Unexcavated |




PROJECT // 4513E - Cambourne to Cambridge Busway

DESCRIPTION // Trench status

Contains OS data © Crown Copyright 2023 Open Government Licence 3.0

WP 230621

FIGURE // Trench Status 3/5



- | | | | |
|--|-------------------|---|-------------|
| The Site | | Trench Status | |
|  | Site Boundary |  | Excavated |
|  | Services - Buffer |  | Unexcavated |




PROJECT // 4513E - Cambourne to Cambridge Busway

DESCRIPTION // Trench status


Contains OS data © Crown Copyright 2023 Open Government Licence 3.0

WP 230621

FIGURE // Trench Status 4/5



- | The Site | | Trench Status | |
|--|-------------------|---|-----------|
|  | Site Boundary |  | Excavated |
|  | Services - Buffer | | |





PROJECT // 4513E - Cambourne to Cambridge Busway

DESCRIPTION // Trench status



Contains OS data © Crown Copyright 2023 Open Government Licence 3.0

WP 230621

FIGURE // Trench Status 5/5



- | The Site | | Trench Status | |
|--|-------------------|---|-------------|
|  | Site Boundary |  | Excavated |
|  | Services - Buffer |  | Unexcavated |



PROJECT // 4513E - Cambourne to Cambridge Busway

DESCRIPTION // Trench status

Contains OS data © Crown Copyright 2023 Open Government Licence 3.0

WP 230712



62-64 Hills Road
Cambridge
CB2 1LA

wsp.com